Outgoing coo70011

From:

Steve Demczak

To:

Charles Reynolds; Suzanne Steab 6/22/2010 8:26 AM

Date:

Subject: May Insp Report 20100622084411.pdf



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Charles Reynolds Resident Agent
OGM	Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070011		
Inspection Type:	COMPLETE		
Inspection Date:	Tuesday, May 25, 2010		
Start Date/Time:	5/25/2010 10:00:00 AM		
End Date/Time:	5/25/2010 3:00:00 PM		
Last Inspection:	Monday, April 05, 2010		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 2376

Types of Operations

Date

Accepted by: jhelfric 6/21/2010

Permitee: HIAWATHA COAL CO INC Operator: HIAWATHA COAL CO INC

Site: HIAWATHA MINE COMPLEX

Address: PO BOX 1240, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

urr	ent	Acr	ead	68
٠	~	, ,	uy	CO.

12,177.00	Total Permitted
290.00	Total Disturbed
95.90	Phase I
	Phase II
	Phase III

Mineral Ownership

✓ Federal ✓ Underground ✓ State ☐ Surface ☐ County Loadout **V** Fee Processing ☐ Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Where ideas connect

Tuesday, June 01, 2010

Permit Number: C0070011 Inspection Type: COMPLETE

Inspection Date: Tuesday, May 25, 2010

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	✓		V	
3.	Topsoil	V		V	
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V			
4.d	Hydrologic Balance: Water Monitoring	V		V	
4.e	Hydrologic Balance: Effluent Limitations	✓		V	
5.	Explosives		V		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		V	
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	✓		V	
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	V		V	
13.	Revegetation	V			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓		✓	
16.a	Roads: Construction, Maintenance, Surfacing	✓			
16.b	Roads: Drainage Controls	V	· 🔲	V	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		V	
19.	AVS Check	V			
20.	Air Quality Permit	V			
21.	Bonding and Insurance	V		V	
22.	Other				

Permit Number: C0070011 Inspection Type: COMPLETE

Inspection Date: Tuesday, May 25, 2010

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

SPPC Plan was reviewed and signed by a P.E. on 11/04/2009. The Air Quality Permit is BAQE-502-89. The mining and Reclamation Permit will expire on March 14, 2012. UPDES Permit will expire on December 31, 2014.

2. Signs and Markers

The idientification signs are next to the roads to the mine site.

3. Topsoil

The topsoil piles were inspected with no signs of wind or water erosion.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and would function during a storm event.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected for the first quarter of 2010. No hazardous conditions were reported. The sediment ponds were inspected on March 25, 2010.

4.d Hydrologic Balance: Water Monitoring

Water Monitoring was reported for first quarter of 2010.

4.e Hydrologic Balance: Effluent Limitations

There was no UPDES discharges for the first quarter of 2010.

7. Coal Mine Waste, Refuse Piles, Impoundments

Refuse piles was inspected for the first quarter on March 26, 2010. No hazardous conditions were reported. I inspected the refuse pile and did not see any hazardous conditions.

8. Noncoal Waste

The permittee is in the process of removing scrap metal from the property.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

12. Backfilling And Grading

No backfilling and grading is occurring at the present time.

15. Cessation of Operations

No slurry was being loaded out during the inspection.

Permit Number: C0070011 Inspection Type: COMPLETE

Inspection Date: Tuesday, May 25, 2010

Page 4 of 4

16.b Roads: Drainage Controls

Diversion were open along the road.

18. Support Facilities, Utility Installations

No support facilities were constructed since the last inspection.

21. Bonding and Insurance

The bonding amount is 2.128,000 million dollars. The reclamation agreement was updated but needs both parties signatures. The insurance is by Federal Insurance Agency and expires on March 8, 2011.